

www.asia-inspection-service.com info@asia-inspection-service.com

### **Asia Inspection Service Factory Audit Report**

Factory Audit	Information
Asia Inspection Service Order Number	A2001751022 2
Client Name	Asia Co ectiv
Audit Date	Mar 2, J
Factory Name	JinHuz sicaria Household Co., Ltd

Auditor (s)

Supervision Started at 09:04:23 Mar 02, 2020 GMT

Supervision Complete 12:43:50 Mar 02, 2021 GMT



www.asia-inspection-service.com info@asia-inspection-service.com

Factory Information				
Factory Name				
Year of Establishment	2006			
Address	金华市 y			
Contact Person	Cao Mi then			
Telephone	15) XXX8321			
Email Address				
Number of Employees	300			
Total Production Area (m²)	25000 m²			
Main Product	Outdoor leisure household products			
Production ve se	Raw materials procurement-production processing-packaging			
Monthly P to tio Capacity	120 GP			
Minmun Order Quantity (Unit)	11*40HQ			
Annual Value of Exporting (RMB)	¥0			
Payment Term	т/т			
Shipping Port	Customized			
Sub-supplier Quantity	0			



www.asia-inspection-service.com info@asia-inspection-service.com

# Your people in Asia

### **Current Business Information**

Major Customers	Country (Area)	Turnover (USD/RMB)	Products
Can't provide	Can't provide	\$0	Can't provide



www.asia-inspection-service.com info@asia-inspection-service.com

Factory	/ Organization a	and Staff
ractory	/ Organization d	anu Stan

Administration Department	Manager	1	Staff	
Sales	Manager	1	Staff	29
Department				
Warehouse	Supervisor	1	Sta	5
Purchasing	C		CC /	4
Department	Supervisor	1	aff	1
Technique	C		C+-st	4
Department	Supervisor		Staff	4
Production	Curanic	5	Crott	21.0
Department /	Supervi		Staff	216
QC	Sup	1	Staff	_
Department	Supl to or	1	Stail	5



www.asia-inspection-service.com info@asia-inspection-service.com

# Photo of Asia Inspection Service inspector anti-bribery confirmation





www.asia-inspection-service.com info@asia-inspection-service.com

# Photo of Asia Inspection Service inspector's on-site working records



Photo of Asia Inspection Service inspector anti-bribery confirmation Asia Inspection Service: Mr(s.) Xie (Work ID no. 17867)

> Photo time: 2020-03-02 10:41:30 Location: 龙潭路 XXXX 有限公司



www.asia-inspection-service.com info@asia-inspection-service.com


#### 1. Products





www.asia-inspection-service.com info@asia-inspection-service.com

#### 2. Certificates





www.asia-inspection-service.com info@asia-inspection-service.com





Employee register - Unable to provide: the factory salesman said that the customer only has an order for one container, and the customer said to have a brief understanding of the factory's production and export capacity, so they can only provide some information concerned by the customer, other information cannot be provided



www.asia-inspection-service.com info@asia-inspection-service.com

### 4. Buildings & Workshops






www.asia-inspection-service.com info@asia-inspection-service.com





www.asia-inspection-service.com info@asia-inspection-service.com





www.asia-inspection-service.com info@asia-inspection-service.com





www.asia-inspection-service.com info@asia-inspection-service.com





www.asia-inspection-service.com info@asia-inspection-service.com

### 5. Equipment & Device





www.asia-inspection-service.com info@asia-inspection-service.com



Equipment-Pressing, forming equipment-65pcs(2/2)



Equipment-Welding, shot blasting equipment -15 sets(1/2)



Equipment-Welding, shot blasting equipment -15 sets(2/2)



Equipment-Powder coating line-1set

### **End of Report**