

www.asia-inspection-service.com info@asia-inspection-service.com

Asia Inspection Service Product Inspection Report

| Product De | scription |
|--------------------------------------|------------------------|
| Asia Inspection Service Order Number | A190146610016 |
| Client Name | XXXXX |
| Inspection Date | Jar (1, 2, ?1 |
| Factory Name | Wuji g (X cile Co, Ltd |
| Product Category | Textil & Raw Material |
| Product Name | Towel |
| Style/Model Number | Towel Dark Grey |
| P/O Number | Dark Grey |
| Order Quantity | 2600 (Meters) |
| Actual Shipmer Qu city | 2667 (Meters) |

| ect (s) | Mr. Wei (33594) |
|-------------------------|---------------------------|
| Inspection Started at | 09:18:13 Jan 11, 2021 GMT |
| Insportion Completed at | 14:17:34 Jan 12, 2021 GMT |
| Sampling Standard | Full Inspection |
| Sample Size (Meters) | 2600 |



www.asia-inspection-service.com info@asia-inspection-service.com

| | C |
|---------------------|--|
| | Summary |
| Client Requirements | |
| Remarks | For the inspection, vendor provided and ple, didn't provide packing list The Actual Shipment Quantit 26.7 meters. The packed quantit 3.3 lls. Detailed shipping reackage infor polybag with label. For style to ell Grey, QC inspected 2600Meters ailed info as four-point strem sheed Broken picks, Barre, Holes, Bank Phre, Holes, Barre, Broken picks, Neps, Loose Thread. Full Width 152cm; Cuttable Width 149cm. On-site test as below: Scan Test-2rolls-Pass Roll Length Test No shortage Colour Shade Test - 53rolls – grade 3~4 Side to Middle Shade Test - 4lots - grade 4 Colour Fastness Test - 4lots - grade 4 Fabric Weight Test - 249~256gsm Below pending points were found during inspection, need client check and confirm: Colour shade was grade 3~4. The colour of bulk was darker than the sample. |



www.asia-inspection-service.com info@asia-inspection-service.com

Photo of Asia Inspection Service inspector anti-bribery confirmation





www.asia-inspection-service.com info@asia-inspection-service.com

Photo of Asia Inspection Service inspector's on-site working records



Photo of Asia Inspection Service inspector's on-site working records
TradeAider Inspector: Mr(s). Wei (Work ID no. 33594)
Photo time:2021-01-11 10:19:19 Location:江苏省苏州市吴江区 XXXX



www.asia-inspection-service.com info@asia-inspection-service.com





www.asia-inspection-service.com info@asia-inspection-service.com

2. Sampling Rolls






www.asia-inspection-service.com info@asia-inspection-service.com






www.asia-inspection-service.com info@asia-inspection-service.com





www.asia-inspection-service.com info@asia-inspection-service.com


5. Accessories






www.asia-inspection-service.com info@asia-inspection-service.com

6. Workmanship






www.asia-inspection-service.com info@asia-inspection-service.com






www.asia-inspection-service.com info@asia-inspection-service.com





www.asia-inspection-service.com info@asia-inspection-service.com





www.asia-inspection-service.com info@asia-inspection-service.com


7. Roll Width





www.asia-inspection-service.com info@asia-inspection-service.com

8. Test





www.asia-inspection-service.com info@asia-inspection-service.com






www.asia-inspection-service.com info@asia-inspection-service.com





www.asia-inspection-service.com info@asia-inspection-service.com





www.asia-inspection-service.com info@asia-inspection-service.com

